ZE

 \supset

CODE

W

Ш

 \Box

77 J

N (A

> ω ω

۵ \bigcirc

> PRP DGG

0 75

ത

ഗ

APPROVED:

DGG

2

76

S

SEMI!

≺ / ₽ I

Z G NST OF

CAB!

ĖП SNO

ITLE:

 \bigcirc

76

3301 Ele West Palm

way ,33407

mc.

Microwave, 3301 Electronics Wast Palm Beach,FL.3

 \perp

ഗ

 \preceq

SCR Ħ

 \square

É

APPR

刀 円 \bigcap

DRAWN: CKED

DWC

у́ 4 200

./95

 \mathcal{O}

 ∞

ιà íП

Microwave

3301 ELECTRONICS WAY WEST PALM BEACH, FL. 33407

Microwave

3301 ELECTRONICS WAY WEST PALM BEACH, FL. 33407

CONNECTOR TYPE....CABLED SOLDER ATTACHMENT

CABLE TYPE.....SEMI-RIGID CABLE

CONNECTOR TYPE....CABLED SOLDER ATTACHMENT

CABLE TYPE.....SEMI-RIGID CABLE

NOTE:

TO MINIMIZE CABLE INSULATOR GROWTH DURING SOLDER OPERATION NORMALIZE CABLE (THERMAL SHOCK CABLE PER MIL-STD-202, METHOD 107, COND. B) PRIOR TO FINAL TRIM. PARA.1.0.

NOTE:


TO MINIMIZE CABLE INSULATOR GROWTH DURING SOLDER OPERATION NORMALIZE CABLE (THERMAL SHOCK CABLE PER MIL-STD-202, METHOD 107, COND. B) PRIOR TO FINAL TRIM. PARA.1.0.


CABLE PREPARATION

1.0 PREPARE CABLE END
1.1 TRIM CABLE OUTER CONDUCTOR AND DIELECTRIC
TO DIMENSIONS SHOWN. CHAMFER INNER CONDUCTOR
TO CONFIGURATION SHOWN (FILING IS ACCEPTABLE).
DO NOT NICK INNER CONDUCTOR.

CABLE PREPARATION


1.0 PREPARE CABLE END
1.1 TRIM CABLE OUTER CONDUCTOR AND DIELECTRIC
TO DIMENSIONS SHOWN. CHAMFER INNER CONDUCTOR
TO CONFIGURATION SHOWN (FILING IS ACCEPTABLE).
DO NOT NICK INNER CONDUCTOR.






FINAL ASSEMBLY

FINAL ASSEMBLY



- 2.0 SOLDER CABLE TO BODY
 - 2.1 INSTALL TRIMMED CABLE INTO CONNECTOR BODY SO THAT CABLE BOTTOMS ON CONNECTOR BODY SHOULDER AS SHOWN.
 - 2.2 SOFT SOLDER CABLE OUTER CONDUCTOR TO CONNECTOR BODY.



- SOLDER CABLE TO BODY
 - 2.1 INSTALL TRIMMED CABLE INTO CONNECTOR BODY SO THAT CABLE BOTTOMS ON CONNECTOR BODY SHOULDER AS SHOWN.
 - 2.2 SOFT SOLDER CABLE OUTER CONDUCTOR TO CONNECTOR BODY.

CABLE ASSEMBLY INSTRUCTIONS 300-80-031.

CABLE ASSEMBLY INSTRUCTIONS 300-80-031.